



CRITERIA FOR BIOLOGICAL GROWTHS ON WALLS
& GENERAL KEY PLAN


SMALL





MEDIUM



LARGE






LARGEST



LEGEND:

- EXTERIOR ELEVATION
- INTERIOR ELEVATION
- OUTER WALLS
- INNER WALLS


 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY:-  ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL:  ENGR. EDUARDO C. MILLALON JR. PLANNING OFFICER V	APPROVED BY:  CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT GENERAL KEY PLAN CRITERIA FOR BIOLOGICAL GROWTH	SHEET NO. A-01
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY:  ENGR. LOVELIE D. ABARQUEZ ENGINEER II						




SMALL - 1



SMALL - 4





INNER WALL - INTERIOR (ELEVATION 1B)



KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE :	PREPARED BY : ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK		LOCATION:	CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	INNER WALL - INTERIOR (ELEVATION 1B) KEY PLAN	A-02
GEN. LUNA & SAN MARCELINO STREET, MANILA							




SMALL - 1



SMALL - 8




INNER WALL - INTERIOR (ELEVATION 3B)




KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL:  ENGR. EDUARDO C. VILLALÓN JR. PLANNING OFFICER V		APPROVED BY:  CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT INNER WALL - INTERIOR (ELEVATION 3B) KEY PLAN	SHEET NO. A-03
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY:  ENGR. LOVELLE D. ABARQUEZ ENGINEER II									



INNER WALL - INTERIOR (ELEVATION 4B)

MEDIUM - 1




KEY PLAN


NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA (ENGINEER)	RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER III	APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT: INNER WALL - INTERIOR (ELEVATION 4B) KEY PLAN	SHEET NO.: A-04
NATIONAL PARKS DEVELOPMENT COMMITTEE		LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ (ENGINEER II)				





SMALL - 9



INNER WALL - INTERIOR (ELEVATION 5B)




KEY PLAN



 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA			
NATIONAL PARKS DEVELOPMENT COMMITTEE			
PROJECT TITLE :		PREPARED BY :	
PREVENTIVE MAINTENANCE OF PACO PARK		ENGR. JOHN MATTHEW M. LACEDA <i>(Signature)</i> ENGINEER I	
LOCATION:		CHECKED BY :	
GEN. LUNA & SAN MARCELINO STREET, MANILA		ENGR. LOVELLE D. ABARQUEZ <i>(Signature)</i> ENGINEER II	
		RECOMMENDING APPROVAL:	
		ENGR. EDUARDO C. VILLALON JR. <i>(Signature)</i> PLANNING OFFICER V	
		APPROVED BY:	
		CECILLE A. LORENZANA-ROMERO <i>(Signature)</i> EXECUTIVE DIRECTOR III	
		SHEET CONTENT	
		INNER WALL - INTERIOR (ELEVATION 6B) KEY PLAN	
		SHEET NO.	
		A-06	



SMALL - 3



SMALL - 3



SMALL - 2




SMALL - 1




INNER WALL - INTERIOR (ELEVATION 8B)



SMALL - 4



SMALL - 1




KEY PLAN

NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA	
PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		CHECKED BY: ENGR. LOVELLIE D. ABARQUEZ ENGINEER II		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV	
APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT: INNER WALL - INTERIOR (ELEVATION 8B) KEY PLAN		SHEET NO.: A-08	






SMALL - 3, MEDIUM - 1






INNER WALL - EXTERIOR (ELEVATION 1B)




KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE :	PREPARED BY : ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL :	APPROVED BY :	SHEET CONTENT	SHEET NO.
		PREVENTIVE MAINTENANCE OF PACO PARK	CHECKED BY : ENGR. LOVELLE D. ABARQUEZ ENGINEER II	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	INNER WALL - EXTERIOR (ELEVATION 1B) KEY PLAN	A-09
		LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA					





INNER WALL - EXTERIOR (ELEVATION 6B)




KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT INNER WALL - EXTERIOR (ELEVATION 6B) KEY PLAN	SHEET NO. A-11
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II				



INNER WALL - EXTERIOR (ELEVATION 7B)



KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA	PROJECT TITLE :	PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL:  ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV	APPROVED BY:  CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT	SHEET NO.
	PREVENTIVE MAINTENANCE OF PACO PARK	CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II			INNER WALL - EXTERIOR (ELEVATION 7B)	A-12
	LOCATION:				KEY PLAN	


GEN. LUNA & SAN MARCELINO STREET, MANILA



MEDIUM - 1



INNER WALL - EXTERIOR (ELEVATION 8B)



KEY PLAN

NATIONAL PARKS DEVELOPMENT COMMITTEE NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK		ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. VILLALBA ON JR. PLANNING OFFICER V	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	INNER WALL - EXTERIOR (ELEVATION 8B)	KEY PLAN	A-13
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ ENGINEER II					



SMALL - 3



SMALL - 1



SMALL - 1



SMALL - 1




SMALL - 2



MEDIUM - 1



MEDIUM - 1



OUTER WALL - INTERIOR (ELEVATION 1A)



MEDIUM - 1




SMALL - 2



SMALL - 2



SMALL - 2



KEYPLAN

PROJECT TITLE :

NATIONAL PARKS DEVELOPMENT
COMMITTEE

T.M. KALAW, MANILA

PREVENTIVE MAINTENANCE
OF PACO PARK

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY :

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY :

ENGR. LOVELIE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL :

ENGR. EDUARDO C. VILLADON JR.
PLANNING OFFICER V

APPROVED BY :

CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET CONTENT



OUTER WALL -
INTERIOR
(ELEVATION 1A)

KEY PLAN

SHEET NO.

A-14






 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA	PROJECT TITLE :		PREPARED BY :	RECOMMENDING APPROVAL :	APPROVED BY :	SHEET CONTENT	SHEET NO.
	PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		ENGR. JOHN MATTHEW M. LACEDA ENGINEER				
			CHECKED BY :				
			ENGR. LOVELLE D. ABARQUEZ ENGINEER II				
			ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV				
		CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	OUTER WALL - INTERIOR (ELEVATION 2A) KEY PLAN	A-15			




SMALL - 1



SMALL - 2




SMALL - 1



SMALL - 1



SMALL - 2




OUTER WALL - INTERIOR (ELEVATION 3A)

SMALL - 2, MEDIUM - 2



LARGE - 1




KEYPLAN
3A

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA	PROJECT TITLE :	PREPARED BY :	RECOMMENDING APPROVAL :	APPROVED BY :	SHEET CONTENT	SHEET NO.
	PREVENTIVE MAINTENANCE OF PACO PARK	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. MICALON JR. PLANNING OFFICER V	CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	OUTER WALL - INTERIOR (ELEVATION 3A) KEY PLAN	A-16
LOCATION:						
GEN. LUNA & SAN MARCELINO STREET, MANILA						



OUTER WALL - INTERIOR (ELEVATION 6A)



SMALL - 2




SMALL - 1




MEDIUM - 1




MEDIUM - 2



KEY PLAN


 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK	PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL:  ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	APPROVED BY:  CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT OUTER WALL - INTERIOR (ELEVATION 6A) KEY PLAN	SHEET NO. A-17
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA							



SMALL - 1



OUTER WALL - INTERIOR (ELEVATION 7A)




KEY PLAN

NATIONAL PARKS DEVELOPMENT COMMITTEE NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE :	PREPARED BY :	RECOMMENDING APPROVAL :	APPROVED BY :	SHEET CONTENT	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	CHECKED BY : ENGR. LOVELLE D. ABARQUEZ ENGINEER II	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	OUTER WALL - INTERIOR (ELEVATION 6A) KEY PLAN	A-18



OUTER WALL - INTERIOR (ELEVATION 8A)




KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
		PREVENTIVE MAINTENANCE OF PACO PARK	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. MILLALON JR. PLANNING OFFICER I	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II	OUTER WALL - INTERIOR (ELEVATION 8A)	A-19
LOCATION:		GEN. LUNA & SAN MARCELINO STREET, MANILA	CHECKED BY:			KEY PLAN	
			ENGR. LOVELLE D. ABARQUEZ ENGINEER II				



OUTER WALL - EXTERIOR (ELEVATION 1A)



KEY PLAN

 NATIONAL PARKS DEPARTMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE :		PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK		ENGR. JOHN MATTHEW M. LACEDA ENGINEER I					OUTER WALL - EXTERIOR (ELEVATION 1A)	A-20
GEN. LUNA & SAN MARCELINO STREET, MANILA		ENGR. LOVELIE D. ABARQUEZ ENGINEER II						



MEDIUM - 2




MEDIUM - 1



SMALL - 3



OUTER WALL - EXTERIOR (ELEVATION 2A)



KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT:	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK		ENGR. JOHMY MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	OUTER WALL - EXTERIOR (ELEVATION 2A)	KEY PLAN	A-21
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ ENGINEER II					

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR.		APPROVED BY: CECILLE A. LORENZANA-ROMERO		SHEET CONTENT: OUTER WALL - EXTERIOR (ELEVATION 3A)		SHEET NO. A-22	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ		ENGINEER II		PLANNING OFFICER IV		EXECUTIVE DIRECTOR III					



OUTER WALL - EXTERIOR (ELEVATION 3A)



SMALL - 1



MEDIUM - 1



MEDIUM - 2



SMALL - 1



LARGE - 1



SMALL - 1



LARGE - 1



SMALL - 4



MEDIUM - 1





MEDIUM - 2





SMALL - 1

KEY PLAN





OUTER WALL - EXTERIOR (ELEVATION 4A)



KEY PLAN



NATIONAL PARKS DEVELOPMENT COMMITTEE

T.M. KALAW, MANILA

PROJECT TITLE:

PREVENTIVE MAINTENANCE OF PACO PARK

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA

CHECKED BY:

ENGR. LOVELLE D. ABARQUEZ

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.

PLANNING OFFICER V

APPROVED BY:

CECILE A. LORENZANA-ROMERO

EXECUTIVE DIRECTOR II

SHEET CONTENT

OUTER WALL - EXTERIOR (ELEVATION 4A)

KEY PLAN

SHEET NO.

A-23




SMALL - 4



MEDIUM - 1



SMALL - 2




MEDIUM - 1



MEDIUM - 1



OUTER WALL - EXTERIOR (ELEVATION 5A)




SMALL - 2



MEDIUM - 1



MEDIUM - 2



KEY PLAN



NATIONAL PARKS DEVELOPMENT
COMMITTEE

T.M. KOLAWY, MANILA

PROJECT TITLE:

PREVENTIVE MAINTENANCE
OF PACO PARK

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY:

ENGR. LOVELIE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.
PLANNING OFFICER IV

APPROVED BY:

CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III




SHEET CONTENT

OUTER WALL -
EXTERIOR
(ELEVATION 5A)

KEY PLAN


SHEET NO.

A-24




LARGE - 1

LARGE - 1



OUTER WALL - EXTERIOR (ELEVATION 6A)



KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT OUTER WALL - EXTERIOR (ELEVATION 6A) KEY PLAN		SHEET NO. A-25	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA				CHECKED BY: ENGR. LOVELIE D. ABARQUEZ ENGINEER II									



LARGE - 1



MEDIUM - 1



SMALL - 1



MEDIUM - 1



LARGE - 1



SMALL - 2




OUTER WALL - EXTERIOR (ELEVATION 7A)



LARGE - 1




LARGE - 1



MEDIUM - 1



SMALL - 2



KEY PLAN



**NATIONAL PARKS DEVELOPMENT
COMMITTEE**
T.M. KALAW, MANILA

PROJECT TITLE :

**PREVENTIVE MAINTENANCE
OF PACO PARK**

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY:

ENGR. LOVELLE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.
PLANNING OFFICER V

APPROVED BY:

CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET NO.

SHEET CONTENT

**OUTER WALL -
EXTERIOR
(ELEVATION 7A)**

KEY PLAN

A-26




MEDIUM - 2

MEDIUM - 4

MEDIUM - 1




OUTER WALL - EXTERIOR (ELEVATION 8A)



KEY PLAN

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA PROJECT TITLE : PREPARED BY :		PREVENTIVE MAINTENANCE OF PACO PARK ENGR. JOHN MATTHEW M. LACEDA (ENGINEER I) LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT OUTER WALL - EXTERIOR (ELEVATION 8A) KEY PLAN	SHEET NO. A-27
---	--	--	--	---	--	---	--




SMALL - 1




SMALL - 1




FRONT ELEVATION




SMALL - 4



SMALL - 2



REAR ELEVATION



SMALL - 3



NATIONAL PARKS DEVELOPMENT
COMMITTEE
T.M. KALAW, MANILA

PROJECT TITLE :

PREVENTIVE MAINTENANCE
OF PACO PARK

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY:

ENGR. LOVELIE D. ABARQUEZ
ENGINEER III

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.
PLANNING OFFICER V

APPROVED BY:

CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET CONTENT

CHAPEL FRONT
AND REAR
ELEVATION

SHEET NO.

A-28




SMALL - 1




SMALL - 1, MEDIUM - 2



SMALL - 1



LEFT-SIDE ELEVATION




MEDIUM - 1




SMALL - 1




SMALL - 3, MEDIUM - 3



SMALL - 8



RIGHT-SIDE ELEVATION



SMALL - 19



SMALL - 1



SMALL - 1



NATIONAL PARKS DEVELOPMENT
COMMITTEE

T.M. KALAW, MANILA

PROJECT TITLE:

PREVENTIVE MAINTENANCE
OF PACO PARK

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY:

ENGR. LOVELIE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.
PLANNING OFFICER V

APPROVED BY:

CECILLE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET CONTENT


CHAPEL LEFT
AND RIGHT-SIDE
ELEVATION

SHEET NO.

A-29



BALUSTRADE 01 (Left Side facing Chapel)



BALUSTRADE 03 (Left Side facing Chapel)




BALUSTRADE 02 (Left Side facing Chapel)



BALUSTRADE 04 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY* ENGR. JOHN MATTHEW M. LACEDA (ENGINEER I)		RECOMMENDING APPROVAL:		APPROVED BY:		SHEET CONTENT		SHEET NO.	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ (ENGINEER II)		ENGR. EDUARDO C. MICALON JR. PLANNING OFFICER V		CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		LEFT-SIDE FACING CHAPEL BALUSTRADE 1-4 (CONDITION MAPPING)		A-30			



BALUSTRADE 05 (Left Side facing Chapel)



BALUSTRADE 07 (Left Side facing Chapel)



BALUSTRADE 06 (Left Side facing Chapel)




BALUSTRADE 08 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. MALLALON JR. PLANNING OFFICER V		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: LEFT-SIDE FACING CHAPEL BALUSTRADE 5-8 (CONDITION MAPPING)		SHEET NO.: A-31	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ ENGINEER II											



BALUSTRADE 09 (Left Side facing Chapel)



BALUSTRADE 11 (Left Side facing Chapel)



BALUSTRADE 10 (Left Side facing Chapel)



BALUSTRADE 12 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA <i>(Signature)</i> ENGINEER I CHECKED BY: ENGR. LOVELIED. ABARQUEZ <i>(Signature)</i> ENGINEER II		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. <i>(Signature)</i> PLANNING OFFICER IV		APPROVED BY: <i>(Signature)</i> CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT LEFT-SIDE FACING CHAPEL BALUSTRADE 9-12 (CONDITION MAPPING)		SHEET NO. A-32	
---	--	---	--	---	--	---	--	--	--	---	--	-------------------------------------	--



BALUSTRADE 13 (Left Side facing Chapel)



BALUSTRADE 15 (Left Side facing Chapel)



BALUSTRADE 14 (Left Side facing Chapel)



BALUSTRADE 16 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA (ENGINEER I) CHECKED BY: ENGR. LOVELLE D. ABARQUEZ (ENGINEER II)		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. (PLANNING OFFICER I)		APPROVED BY: CECILLE A. LORENZANA-ROMERO (EXECUTIVE DIRECTOR II)		SHEET CONTENT LEFT-SIDE FACING CHAPEL BALUSTRADE 13-16 (CONDITION MAPPING)		SHEET NO. A-33	
---	--	---	--	--	--	--	--	---	--	---	--	-------------------------------------	--



BALUSTRADE 17 (Left Side facing Chapel)



BALUSTRADE 19 (Left Side facing Chapel)



BALUSTRADE 18 (Left Side facing Chapel)



BALUSTRADE 20 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER		RECOMMENDING APPROVAL: ENGR. EDUARDO C. MALLON JR. PLANNING OFFICER I		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT: LEFT-SIDE FACING CHAPEL BALUSTRADE 17-20 (CONDITION MAPPING)		SHEET NO. A-34	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER I											



BALUSTRADE 21 (Left Side facing Chapel)



BALUSTRADE 23 (Left Side facing Chapel)




BALUSTRADE 22 (Left Side facing Chapel)



BALUSTRADE 24 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:		RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
PREVENTIVE MAINTENANCE OF PACO PARK		LOCATION:	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		LEFT SIDE FACING CHAPEL BALUSTRADE 21-24 (CONDITION MAPPING)	A-35
GEN. LUNA & SAN MARCELINO STREET, MANILA			ENGR. LOVELLIE D. ABARQUEZ ENGINEER II		CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II			



BALUSTRADE 25 (Left Side facing Chapel)



BALUSTRADE 27 (Left Side facing Chapel)



BALUSTRADE 26 (Left Side facing Chapel)



BALUSTRADE 28 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT LEFT-SIDE FACING CHAPEL BALUSTRADE 25-28 (CONDITION MAPPING)		SHEET NO. A-36	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											



BALUSTRADE 29 (Left Side facing Chapel)



BALUSTRADE 31 (Left Side facing Chapel)



BALUSTRADE 30 (Left Side facing Chapel)



BALUSTRADE 32 (Left Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO D. MILLAN JR. PLANNING OFFICER V		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: LEFT-SIDE FACING CHAPEL BALUSTRADE 29-32 (CONDITION MAPPING)		SHEET NO. A-37	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE P. ABARQUEZ ENGINEER II											



BALUSTRADE 33 (Left Side facing Chapel)



BALUSTRADE 34 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. MILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: LEFT & RIGHT-SIDE FACING CHAPEL BALUSTRADE 33-34 (CONDITION MAPPING)		SHEET NO. A-38	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											



BALUSTRADE 35 (Right Side facing Chapel)



BALUSTRADE 37 (Right Side facing Chapel)



BALUSTRADE 36 (Right Side facing Chapel)



BALUSTRADE 38 (Right Side facing Chapel)

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL BALUSTRADE 35-38 (CONDITION MAPPING)	SHEET NO. A-39
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELIE D. ABARQUEZ ENGINEER I									



BALUSTRADE 39 (Right Side facing Chapel)



BALUSTRADE 41 (Right Side facing Chapel)



BALUSTRADE 40 (Right Side facing Chapel)



BALUSTRADE 42 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. WILALON JR. PLANNING OFFICER V		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: RIGHT-SIDE FACING CHAPEL BALUSTRADE 39-42 (CONDITION MAPPING)		SHEET NO. A-40	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER V											



BALUSTRADE 47 (Right Side facing Chapel)



BALUSTRADE 49 (Right Side facing Chapel)



BALUSTRADE 48 (Right Side facing Chapel)



BALUSTRADE 50 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching

DISCLAIMER: Not all damages are visible or seen in one figure of balustrade

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: RIGHT-SIDE FACING CHAPEL BALUSTRADE 46-50 (CONDITION MAPPING)		SHEET NO.: A-42	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											



BALUSTRADE 51 (Right Side facing Chapel)



BALUSTRADE 53 (Right Side facing Chapel)



BALUSTRADE 52 (Right Side facing Chapel)



BALUSTRADE 54 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUWA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL BALUSTRADE 51-54 (CONDITION MAPPING)		SHEET NO. A-43	
---	--	---	--	--	--	---	--	---	--	---	--	-------------------------------------	--



BALUSTRADE 55 (Right Side facing Chapel)



BALUSTRADE 57 (Right Side facing Chapel)



BALUSTRADE 56 (Right Side facing Chapel)



BALUSTRADE 58 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT: RIGHT-SIDE FACING CHAPEL BALUSTRADE 55-58 (CONDITION MAPPING)		SHEET NO. A-44	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											



BALUSTRADE 59 (Right Side facing Chapel)



BALUSTRADE 61 (Right Side facing Chapel)



BALUSTRADE 60 (Right Side facing Chapel)




BALUSTRADE 62 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		APPROVED BY: Cecille A. Lorenzana-Romero EXECUTIVE DIRECTOR II		SHEET CONTENT: RIGHT-SIDE FACING CHAPEL BALUSTRADE 59-62 (CONDITION MAPPING)		SHEET NO.: A-45	
LOCATION: GEN. LUNA & SAN MARCEL NO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											



BALUSTRADE 63 (Right Side facing Chapel)



BALUSTRADE 65 (Right Side facing Chapel)




BALUSTRADE 64 (Right Side facing Chapel)



BALUSTRADE 66 (Right Side facing Chapel)

LEGEND: ☒ Loose Plaster ☒ Repair/ Patching *DISCLAIMER: Not all damages are visible or seen in one figure of balustrade*

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA <i>(Signature)</i> ENGINEER I CHECKED BY: ENGR. LOVELLE D. ABARQUEZ <i>(Signature)</i> ENGINEER II		RECOMMENDING APPROVAL: ENGR. EDUARDO C. MILLALON JR. <i>(Signature)</i> PLANNING OFFICER APPROVED BY: CECILLE A. LORENZANA-ROMERO <i>(Signature)</i> EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT SIDE FACING CHAPEL BALUSTRADE 63-66 (CONDITION MAPPING)		SHEET NO. A-46	
---	--	--	--	--	--	---	--	---	--	-------------------------------------	--



KEY PLAN

LEGEND:


- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)



PILASTER/ CAPITAL - 01



PILASTER/ CAPITAL - 02




PILASTER/ CAPITAL - 03



PILASTER/ CAPITAL - 04


 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA (ENGINEER)		RECOMMENDING APPROVAL: ENGR. EDUARDO Q. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 1-4 (CONDITION MAPPING)		SHEET NO. A-47	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ (ENGINEER)											



KEY PLAN






LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)



PILASTER/ CAPITAL - 05 PILASTER/ CAPITAL - 06 PILASTER/ CAPITAL - 07 PILASTER/ CAPITAL - 08

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KULAY, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER		RECOMMENDING APPROVAL: ENGR. EDUARDO D. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR II		SHEET CONTENT LEFT SIDE FACING CHAPEL PILASTER & CAPITAL 5-8 (CONDITION MAPPING)	SHEET NO. A-48
---	--	---	--	---	--	--	--	--	--	--	-------------------------------------



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)






PILASTER/ CAPITAL - 09

PILASTER/ CAPITAL - 10

PILASTER/ CAPITAL - 11

PILASTER/ CAPITAL - 12

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 9-12 (CONDITION MAPPING)		SHEET NO. A-49	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER III											



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)






PILASTER/ CAPITAL - 13

PILASTER/ CAPITAL - 14

PILASTER/ CAPITAL - 15

PILASTER/ CAPITAL - 16

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
		PREVENTIVE MAINTENANCE OF PACO PARK	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV	CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 13-16 (CONDITION MAPPING)	A-50
		LOCATION:	CHECKED BY:				
		GEN. LUNA & SAN MARCELINO STREET, MANILA	ENGR. LOVELLE D. ABARQUEZ ENGINEER II				



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)

PILASTER/ CAPITAL - 17




PILASTER/ CAPITAL - 18

PILASTER/ CAPITAL - 19

PILASTER/ CAPITAL - 20

NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 17-20 (CONDITION MAPPING)	SHEET NO. A-51
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II						





KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)


PILASTER/ CAPITAL - 21

PILASTER/ CAPITAL - 22


PILASTER/ CAPITAL - 23

PILASTER/ CAPITAL - 24


 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
		PREVENTIVE MAINTENANCE OF PACO PARK	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER I	CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 21-24 (CONDITION MAPPING)	A-52
		LOCATION:	CHECKED BY:				
		GEN. LUNA & SAN MARCELINO STREET, MANILA	ENGR. LOVELIE D. ABARQUEZ ENGINEER II				




PILASTER/ CAPITAL - 25




PILASTER/ CAPITAL - 26



PILASTER/ CAPITAL - 27



PILASTER/ CAPITAL - 28



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)



**NATIONAL PARKS DEVELOPMENT
COMMITTEE**
T.M. KALAW, MANILA

PROJECT TITLE:

**PREVENTIVE MAINTENANCE
OF PACO PARK**

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY:

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY:

ENGR. LOVELLE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. MALLON JR.
PLANNING OFFICER V

APPROVED BY:






CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET CONTENT

LEFT-SIDE
FACING CHAPEL
PILASTER &
CAPITAL 25-28
(CONDITION
MAPPING)

SHEET NO.

A-53








KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)

PILASTER/ CAPITAL - 29 PILASTER/ CAPITAL - 30 PILASTER/ CAPITAL - 31 PILASTER/ CAPITAL - 32

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V	APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	SHEET CONTENT LEFT-SIDE FACING CHAPEL PILASTER & CAPITAL 29-32 (CONDITION MAPPING)	SHEET NO. A-54
---	--	--	--	---	--	--	--	-------------------------------------



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)

PILASTER/ CAPITAL - 33

PILASTER/ CAPITAL - 34

PILASTER/ CAPITAL - 35

PILASTER/ CAPITAL - 36



**NATIONAL PARKS DEVELOPMENT
COMMITTEE**
T.M. KALAY, MANILA

PROJECT TITLE :

**PREVENTIVE MAINTENANCE
OF PACO PARK**

LOCATION:

GEN. LUNA & SAN MARCELINO STREET, MANILA

PREPARED BY :

ENGR. JOHN MATTHEW M. LACEDA
ENGINEER I

CHECKED BY :

ENGR. LOVELLE D. ABARQUEZ
ENGINEER II

RECOMMENDING APPROVAL:

ENGR. EDUARDO C. VILLALON JR.
PLANNING OFFICER V

APPROVED BY:





CECILIE A. LORENZANA-ROMERO
EXECUTIVE DIRECTOR III

SHEET CONTENT

RIGHT-SIDE
FACING CHAPEL
PILASTER &
CAPITAL 33-36
(CONDITION
MAPPING)

SHEET NO.

A-55



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)





PILASTER/ CAPITAL - 37

PILASTER/ CAPITAL - 38

PILASTER/ CAPITAL - 39

PILASTER/ CAPITAL - 40

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE:	PREPARED BY:	RECOMMENDING APPROVAL:	APPROVED BY:	SHEET CONTENT	SHEET NO.
		PREVENTIVE MAINTENANCE OF PACO PARK	ENGR. JOHN MATTHEW M. LACEDA ENGINEER I	ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV	CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III	RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 37-40 (CONDITION MAPPING)	A-56
		LOCATION:	CHECKED BY:				
		GEN. LUNA & SAN MARCELINO STREET, MANILA	ENGR. LOVELLE D. ABARQUEZ ENGINEER III				



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)






PILASTER/ CAPITAL - 41

PILASTER/ CAPITAL - 42

PILASTER/ CAPITAL - 43

PILASTER/ CAPITAL - 44

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA				
PROJECT TITLE :		PREPARED BY :		
PREVENTIVE MAINTENANCE OF PACO PARK		ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		
LOCATION:		CHECKED BY :		
GEN. LUNA & SAN MARCELINO STREET, MANILA		ENGR. LOVEME D. ABARQUEZ ENGINEER III		
		RECOMMENDING APPROVAL:		APPROVED BY:
		ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III
		RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 41-44 (CONDITION MAPPING)		SHEET NO.
				A-57



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)


PILASTER/ CAPITAL - 45

PILASTER/ CAPITAL - 46

PILASTER/ CAPITAL - 47

PILASTER/ CAPITAL - 48


 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 45-48 (CONDITION MAPPING)		SHEET NO. A-58	
---	--	---	--	--	--	--	--	--	--	---	--	-------------------------------------	--




KEY PLAN

LEGEND:


- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)




PILASTER/ CAPITAL - 49



PILASTER/ CAPITAL - 50




PILASTER/ CAPITAL - 51



PILASTER/ CAPITAL - 52

NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 49-52 (CONDITION MAPPING)	SHEET NO. A-59
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II									







KEY PLAN

LEGEND:


- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)



PILASTER/ CAPITAL - 53



PILASTER/ CAPITAL - 54







PILASTER/ CAPITAL - 55



PILASTER/ CAPITAL - 56

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE : PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY : ENGR. JOHN MATTHEW M. LACEDA (ENGINEER I)		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER V		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 53-56 (CONDITION MAPPING)		SHEET NO. A-60	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ (ENGINEER II)											



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)






PILASTER/ CAPITAL - 57

PILASTER/ CAPITAL - 58

PILASTER/ CAPITAL - 59

PILASTER/ CAPITAL - 60

 NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA (ENGINEER I) CHECKED BY: ENGR. LOVELLE D. ABARQUEZ (ENGINEER I)		RECOMMENDING APPROVAL: ENGR. EDUARDO C. VILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILLE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 57-60 (CONDITION MAPPING)	SHEET NO. A-61
---	--	---	--	---	--	---	--	--	--	---	-------------------------------------



KEY PLAN

LEGEND:

- Loose Plaster
- Column Plaster Repair/ Patching
- Capital Patching (Not Restoration)

PILASTER/ CAPITAL - 61

PILASTER/ CAPITAL - 62

PILASTER/ CAPITAL - 63

PILASTER/ CAPITAL - 64

NATIONAL PARKS DEVELOPMENT COMMITTEE T.M. KALAW, MANILA		PROJECT TITLE: PREVENTIVE MAINTENANCE OF PACO PARK		PREPARED BY: ENGR. JOHN MATTHEW M. LACEDA ENGINEER I		RECOMMENDING APPROVAL: ENGR. EDUARDO C. MILLALON JR. PLANNING OFFICER IV		APPROVED BY: CECILIE A. LORENZANA-ROMERO EXECUTIVE DIRECTOR III		SHEET CONTENT RIGHT-SIDE FACING CHAPEL PILASTER & CAPITAL 61-64 (CONDITION MAPPING)		SHEET NO. A-62	
LOCATION: GEN. LUNA & SAN MARCELINO STREET, MANILA		CHECKED BY: ENGR. LOVELLE D. ABARQUEZ ENGINEER II											

